





Power Off PC




SATA power link to USB HUB




19pin extension cable link between motherboard and HUB



Motherboard USB3.0 data transfer HUB300





after that, all extended ports are functional, and link the extra device by you needs.